

1309cb

# Environmental Protection Report – Vapour Recovery

Premises Spaldwick Avenue St Person seen Mr Ben Fosc

Address \_\_\_\_\_

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**  
 As a result of the inspection your attention is drawn to the following matters:

Inspection conducted on behalf of the District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected  Y / N Satisfactory  Y / N

Notes  
No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES**

Inspected  Y / N Satisfactory  Y / N

Notes  
15/5/19

**c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected  Y / N Satisfactory  Y / N

Notes  
No incidents

**d) STAFF COMPETENCE & TRAINING**

No of Staff  No Questioned

Inspected  Y / N Satisfactory  Y / N

Notes  
No comments

**e) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected  Y / N Satisfactory  Y / N

Notes

Does the site have stage II vapour recovery?  Y / N

Notes

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory  Y / N

Notes

Are procedures in place adequate in the event of any leaks or spillages?  Y / N

Notes

Signed [Signature]

Received by [Signature]

Tel/Email: 01954 284 628

Date/Time: 17/1/20