

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Brampton Hill Connect Person Seen Laura Fursome
 Address Great North Road, Brampton, PE28 4NG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:
 As a result of the inspection of your premises your attention is drawn to the following matters:
None of the major faded signs.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK
 Inspected Y/N Satisfactory Y/N
 Notes: No recent incidents. Incident log available.

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
 Inspected Y/N Satisfactory Y/N
 Notes: Stage 1b cert 17/01/17
Stage 2 cert 08/08/17

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)
 Inspected Y/N Satisfactory Y/N
 Notes: Site register available

d) STAFF COMPETENCE & TRAINING
 No of Staff No Questioned
 Inspected Y/N Satisfactory Y/N
 Notes: Training records in place.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS
 Inspected Y/N Satisfactory Y/N
 Notes: Signs in place although some are faded - advised.
 Does the site have stage II vapour recovery? Y/N
 Notes:

f) SITE MANAGEMENT & OTHER COMMENTS
 Satisfactory Y/N
 Notes: Good management.
 Are procedures in place adequate in the event of any leaks or spillages? Y/N
 Notes:

Signed [Signature] Tel /Email 01954 284631
 Received by L Fursome Date/Time 06/12/17

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.