

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Multihurst Eaton Square Person Seen Chris Cook

Address Great North Road, Eaton Square, St Neots, PE28 2EJ

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**  
As a result of the inspection of your premises your attention is drawn to the following matters:

Site register & tank top warning sign.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected  Y/N Satisfactory  Y/N

Notes: No incidents have occurred. Reporting mechanisms in place.

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected  Y/N Satisfactory  Y/N

Notes: Certificate dated 4/10/16

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected  Y/N Satisfactory  Y/N

Notes: The site register was not available at time of visit. There is a maintenance log.

d) STAFF COMPETENCE & TRAINING

No of Staff  4 No Questioned  1

Inspected  Y/N Satisfactory  Y/N

Notes: Area manager questioned had good knowledge.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected  Y/N Satisfactory  Y/N

Notes: Partial tank tops require VE warning sign - tank 6 SOL missing. Super included.

Does the site have stage II vapour recovery?  Y/N

Notes: Antbarco SK700's.

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory  Y/N

Notes: This site has a new reactor so there is period of settling in required. Area manager - knowledgeable

Are procedures in place adequate in the event of any leaks or spillages?  Y/N

Notes: Daily checks undertaken.

Signed [Signature]

Tel /Email 01954 78631

Received by [Signature]

Date/Time 25/10/17 16:30

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.