

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Burton Bros

Person Seen Chris Tibbles

Address Bury Road, Ramsey

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Drainage gulleys have some debris and should be cleaned

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes:

None reported.

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N

Satisfactory Y/N

Notes:

Certificate dated 27/4/10.

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

Repair work carried out following testing - April '10.

e) STAFF COMPETENCE & TRAINING

No of Staff 3

No Questioned 2

Inspected Y/N

Satisfactory Y/N

Notes:

Regular staff training - staff sign training records.

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

All signage present.

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: Management appears competent. Records are OK.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Some debris in drainage gulleys - not excessive. Requested clearance.

Inspector S Whittington

Date 28/7/2011

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC