

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise TESCO SERVICE STATION

Person Seen LIZ GILSON

Address ABBOTS PIPTON ROAD, HUNTINGDON

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

NO INCIDENTS

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

TESTED 02/06/09

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK

e) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☒ 2

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK

Does the site have stage II vapour recovery? Y/N

Notes:

ALL OK

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

WELL RUN SITE

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

ALL OK

Inspector KIRSTY DRAYCOTT - PETROLEUM

Date 12/10/09

OFFICER CCC TRADING STANDARDS

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC