REPORT - VAPOUR RECOVERY

Premises Toxas Hunharda	Person Seen
Address 15th Lepla Huhrsda PEZEZLA	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
concluded in Scholl of Hulmyda District renal	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N Notes: Notes:	Inspected Y/N Satisfactory Y/N Notes:
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes: 165 in reguste - nething checimental	Notes:
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes:	Notes:
High like toble - discussed	NO training parchase -
signs - au inpluce	revenirs bounins.
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks
Notes: Humahayshar - Adays	or spillages? Y/N Notes:
sher b'hx' it ad purpelises	
Signed Received by	Tel/Email 0/9534 284 628 Menneh. Shepherd Combac yeshire Date/Time Sur wh

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.