ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise EDCO SENICO DICA	Person Seen (10) (West 1841)
Address Berford Road Cyne	obery streets, PE192SA
ridareso Berry Cra response Con Control	350xy, 120x3, 120x3
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
As a result of the inspection of your premises your attention is drawn to the following matters:	
Newsite gened May 2010	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes:
seebelw.	
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY	e) STAFF COMPETENCE & TRAINING No of Staff // No Questioned
CHECKING, INSTALLATION & REPAIR WORK	No or stall 4 No questioned 1
(SITE REGISTER)	Inspected Y/N Satisfactory Y/N
Inspected Y/N Satisfactory Y/N	
Notes:	Notes:
Incident of V.R. loss during delivery extrest fill 17/17/10 Driver district complete drup.	
delivery extres fill	
17/17/10 Drug didnot	
complete drop.	
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
SIGNS	Satisfactory Y/N
Inspected Y/N Satisfactory (Y/N	* *
Notes:	Notes:
	SCHOOL MICHOLD TO THE MOON
Describe the site have to the	A
Does the site have stage II vapour recovery? YN	Are procedures in place adequate in the event of any leaks or spillages? YN
Notes:	Notes:
1100 1 1	
Inspector 1. R. Shophold	Date 6th Dept 2010

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC