

ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Shell Hunningden Person Seen _____
Address Stukley Road, Hunningden, PE29 6HG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Received faxed copy of V.P. inspection cert, as date is same as inspection date phoning company for confirmation.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	Inspected Y/N Notes: N/A	Satisfactory Y/N	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)	Inspected Y/N Notes: Premises brought into compliance following non compliant visit on the 12/10/09.	Satisfactory Y/N
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	Inspected Y/N Notes: N/A	Satisfactory Y/N	e) STAFF COMPETENCE & TRAINING	No of Staff <input type="checkbox"/> No Questioned <input type="checkbox"/>	Satisfactory Y/N
c) VAPOUR RECOVERY CONNECTIONS & SIGNS	Inspected Y/N Notes: N/A	Satisfactory Y/N	f) SITE MANAGEMENT & OTHER COMMENTS	Satisfactory Y/N	
Does the site have stage II vapour recovery? Y/N	Notes: N/A		Notes: N/A	Are procedures in place adequate in the event of any leaks or spillages? Y/N	
			Notes: N/A		

Inspector

Date 22/12/09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC

STORAGE OF PETROLEUM SPIRIT AND MIXTURES

Petroleum (Regulations) Act 1926 and 1936

Health and Safety at Work 1974

**PETROL FILLING STATION
VAPOUR RECOVERY
INSPECTION**

Issued by Johnson Controls Inc
Unit 1, Keenall Road, Off Guinea Road, Trafford Park,
Manchester M17 1SY

Site Details

(Record All Site Information)

HUNTINGDON SHELL
HUNTINGDON
STUKELEY ROAD
HUNTINGDON
CAMBS
PE 186 HG
302827

Vapour Recovery Inspection

(Record All answers)

1	Inspect vent/stack valves/pipework for signs of corrosion, evidence of leaks or any damage	A* B* C*
2	Inspect above and below ground pipework for signs of corrosion, evidence of leaks or any damage	A* B* C*
3	All fill point caps and padlocks (keys available) are both sound and secure	A* B* C*
4	All statutory levels comply with regulations - off site fill point	A* B* C*
5	All statutory levels comply with regulations - direct fill within tank chamber	A* B* C*
6	All statutory levels comply with regulations, both in the chambers and above ground	A* B* C*
7	Ensure the construction is sound, safe for site traffic, ductwork is foam filled and dry of water (inc. cover)	A* B* C*
8	If present (as lancer drivers may carry their own) ensure no damage has occurred to the end connector	N/A A* B* C*
9	Ensure no damage has occurred since previous inspection or any leakage has been reported (check with site)	A* B* C*

Declaration

This certificate must be FULLY completed and signed by the Site Manager - any certificates not correctly completed will be returned.

'A'	MARTIN AUNIS
'B'	121009
'C'	121009
A.J. Add	
ARMAN JAH	