ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Shell Buckdon	Person Seen U/ July Praco
Address Coreal North Rd. Tuck	iden, St Ned-2, PE1950CF
ORCEDVATIONS ADVICE AND DESCRIPTION	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
emailed to me on 24/10/11	
Newsile - fanks etc	20/11
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N Notes:	Inspected Y/N Satisfactory Y/N Notes:
Noincidento	Accurações
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes: All Saff training to be updated
explained to have sechining site resister	
c) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes: AU Ne Knto. New 4knto	Notes: New site Asked fer docs/ training to be updated
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes: No Site
Inspector M.R. SMGPHERD	Date/5/04/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation