REPORT - VAPOUR RECOVERY

Premises April Alus	Person Seen Place Nne V. (Merussi)
Address Roman Road Miles	PE275RT
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
Hondrich an behalf of Kinhyda Dishut Canal	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N Notes:
Notes: Nothing dannated	Date dreat test 30/08/14
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned (Manager)
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N Notes:
Notes: Log to be created	ANOW monagor - Warring required as whate begglan VR. #
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N Notes:
Notes:	Troundane on companie-
	Trouning dane on comparter- unable bacress, suggest matrix openhed and
	sproledal
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes:
hunnah. shipherdo combnososhire. gov. wh	
Signed	Tel /Email <u>01954 284628</u>
Received by Process	Date/Time_2 1/08/13

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

26 13 Mail Warhy achael.