## ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

	Premise PACE Of TUBE	Person Seen My Anton Thomas
	Address Meddy with 10, of 1	160 PGZ75WF
	OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
	As a result of the inspection of your premises your attention is drawn to the following matters:	
	Rups demed re any estars	
	a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
	Inspected Y/N Satisfactory Y/N Notes:	Inspected Y/N Satisfactory (Y/N) Notes:
	Nomaderto	16/c6/11
		+ Presare relief value less + Caye lest completed 26/5/11
$\Theta$	b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	e) STAFF COMPETENCE & TRAINING No of Staff   No Questioned
	Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
	Notes:	Notes:
	Aduce siven =	composed posess checked.
	Aduce siven => Sheed tube added to	as DCD contidled
	sile relible	as DCD controlled
	c) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
	Inspected YN Satisfactory (YIN	Satisfactory YYN
	Notes:	Notes:
	_	
	Does the site have stage II vapour recovery? YN	Are procedures in place adequate in the event of any leaks or spillages? Y/N
	Notes:	Notes:
L		
	Inspector ( )	Date 23/01/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC