

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise BP Little Hampton Person Seen Mr Stefan Brip
Address 23 - 25 London Road, Walsley, Peterborough

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Rectification advice issued incorporating VR non compliances

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

No incidents reported

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N Satisfactory Y/N

Notes:

Expired 08/09/11
Booked in

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

Not recorded ~ VR log book to be updated with inspection details.

e) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected Y/N Satisfactory Y/N

Notes: No staff training records on site, No evidence re competent persons

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Vent 1 requires labeling
Investigate Vent top 2.
VR to be locked

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Under new management ~
rectification advice issued

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

RA needs updating.

Inspector Chapley

Date 07/10/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislative