ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Broadlan barage	Person Seen Mo C Marriso.
Address <u>L89</u> Braedway Yana	dey Peleberaugh PE7 3NR
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
Surepite foregart 'action pen' to be actioned easp esp'	
To back hocke by voits.	
a) INCIDENTE DE VAROUR LEAKE : LOCKE .	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes:
No encidents	
NO LICION (V)	
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned
CHECKING, INSTALLATION & REPAIR WORK	No or Starr
(SITE REGISTER)	Inspected Y/N Satisfactory Y/N
Inspected Y/N Satisfactory Y/N	
Notes:	Ourer uracht takes deliveres
Nouncidents	
100 100 000	small site
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
SIGNS	
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Inspected Y/N Satisfactory Y/N Notes: NELL/100 CA COLO Sold ACAR ACAS - WILL reach to	Notes: As above
fortent tops - Will reed to	170 220 (
CHECK LOVE	
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	
	Notes: small ad site.
\wedge	
1, 1	
Incorporator (1/2 M/97 /	Data (Aliali)

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislatio