

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Droedway Garage Person Seen Mr T Scott
Address 289 Droedway Yorkley Peterborough PE7 3NR

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

inspection conducted on behalf of North York District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

TDI
every three years.

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

d) STAFF COMPETENCE & TRAINING

No of Staff 4 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

small site.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

As per Risk assessment

Signed

[Signature]

Tel /Email

hannah.stephens@
cambridgeshire.gov.uk

Received by

[Signature]

Date/Time

08/01/14

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.