Premise kates (abin (annoct	Person Seen Mr Sarry / ) MMON Q
Address Ap. Book North road	Chesterton, Reterbaciangh, PEZZUJ
	0,(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:  As a result of the inspection of your premises your attention is drawn to the following matters:	
Towhere inspection conducted by H. R. Stephard on behalf	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
No incidents	Notes: Stage 113 testing (ext of apprecial) > Passed. expines 16/08/10
,	
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes:
No annual VR uspection	Has completed compute training but also not aversee delivery
certificade	-> DCD.
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
SIGNS	Satisfactory Y/N
Inspected Y/N Satisfactory Y/N  Notes: Off Sets SEn in place  Mable to lift tank taps	Notes: LP Staff training
Does the site have stage II vapour recover //N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes:
Inspectory Hand.	Date 2010 12:44  Standards  of the inspection. It does not indicate compliance with any legislation.
Hannah Shephard CCC Trading Handerds	
This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.	