| Premise hat Cabin   | Person Seen  |
|---|--|
| Address Brad North Road, Ch   | osteten, Peterbaranh PF7345                                |
|   |  |
| OBSERVATIONS, ADVICE AND RECOMMENDATIONS:  As a result of the inspection of your premises your attention is drawn to the following matters: |  |
| Inspection conducted by M.R. Stepled Combidgedire   |  |
| Madin prendered on behalf of humby ach  |  |
| DISTICT CONCIL.   |  |
| a) INCIDENTS OF VAPOUR LEAKS & LOCKS<br>AND ASSOCIATED LOG BOOK   | d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual) |
| Inspected YN Satisfactor YN   | Inspected Y/N Satisfactory (Y/N                            |
| Notes:  | Notes:   |
| Nomadato  |  |
| 100 () (0(00) () (  |  |
|   |  |
|   |  |
| b) LOG BOOK DETAILING MAINTENANCE,  | e) STAFF COMPETENCE & TRAINING                             |
| EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK   | No of Staff No Questioned                                  |
| (SITE REGISTER)   | a statute of   |
| 1   | Inspected YN Satisfactory YN                               |
| Inspected(Y)N Satisfactory (Y)N Notes:  | Notes:   |
|   | $ \mathcal{D}C\mathcal{D} $                                |
|   |  |
|   |  |
|   |  |
|   | 1) SITE MANAGEMENT & OTHER COMMENTS                        |
| c) VAPOUR RECOVERY CONNECTIONS & SIGNS  |  |
|   | Satisfactory Y/N   |
| Inspected N Satisfactory N Notes:   | Notes:   |
| Notes.  |  |
|   |  |
| Does the site have stage II vapour recovery (Y)N  | Are procedures in place adequate in the event of any leaks |
| Boos the site have enge in experience   | or spillages?(Y/N  |
| Notes:  | Notes:   |
|   |  |
|   |  |
|   | . 1  |
| Inspector MAN   | Date 23/02/12 17/07/12                                     |
| HANNAM SHEPHOND   |  |

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation

Contract for the conduct of process permits: HDC & CCC