

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

**APPENDIX 1**

Premise Shell Buckden

Person Seen Elaine Dudley

Address Great North Road, Buckden

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:  
no incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:  
Tested 03/12/09

**b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:  
ALL OK

**e) STAFF COMPETENCE & TRAINING**

No of Staff ☐ No Questioned 2

Inspected Y/N Satisfactory Y/N

Notes:  
OK

**c) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:  
OK

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:  
OK

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector KIRSTY DRAYCOTT PETROLEUM  
OFFICER CCC TRAINING STANDARDS

Date 16/02/2010

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC