

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Shell Buckdon Person Seen Leanna
Address Great North Road Buckdon PE19 5XE

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of Humberdon District
Council by Hannah Shepherd Trading Standards

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

d) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

RA and seen. Not all becoming on
site - competent persons to be updated

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email 01954 284628

Received by _____

Date/Time 11/07/13

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.