ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise/ Noons Selvice Sanca Person Seen W Consa	
Address 66-76 Cembridge Shoot, St Neds PE19 1PS	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK Inspected (Y/N Satisfactory Y/N Notes:	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual) Inspected YN Satisfactory N Notes:
No unadento	Notes.
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER) Inspected Y/N Satisfactory Y/N Notes:	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned Inspected IN Satisfactory IN Notes: CMY 2 PUSCOS Parks delivery
c) VAPOUR RECOVERY CONNECTIONS & SIGNS Inspected Y/N Satisfactory (Y/N Notes:	f) SITE MANAGEMENT & OTHER COMMENTS Satisfactory YAN Notes:
Does the site have stage II vapour recovery? Y/N Notes:	Are procedures in place adequate in the event of any leaks or spillages? Y/N Notes:
Inspector Mind	Date 6 100 200

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.