

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Total. Person Seen Jim Bishop.
Address Landan Road, St Ives.

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

VR Notices required on Tanks 1 & 3.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes: Slight diesel leak.
Repair work carried out.
Tested & certified.

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes: Certificate dated 27/4/09.

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes: All OK - Work to
exchange tanks carried
out.

e) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes: Competency Certificates
inspected.

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes: VR Notices required on
tanks 1 & 3.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes: Recent work to exchange
tanks has been carried out.
Assurance given that VR Notices
will be put in place.

Are procedures in place adequate in the event of any leaks
or spillages? ☒ Y/N

Notes: Slight diesel leak reported
- Repaired and certified.

Inspector  Date 20/11/2009.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC