

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Malthus Hemmingsford Person Seen M Kumar
Address London Road Stives PC27 5AN

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of Hemmingsford
District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing recorded

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

Gas tested 29/09/12
Re Due 28/09/13

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing recorded

d) STAFF COMPETENCE & TRAINING

No of Staff 5 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

Advice that Nam Denthirasa
receives full petrol training

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

only able to lift tank top
3 & 4. Tank 3 requires
Vapour recovery sign

Does the site have stage II vapour recovery? Y/N

Notes:

Please ensure all tanks
have appropriate Vapour
recovery sign

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

organised documentation

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

old site

Signed C. Lipley

Tel /Email 01454 284 620

Received by P. M. D. P.

Date/Time 23/04/13 1305

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.