

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Shell Hunningdon

Person Seen David

Address Stuckeley road Hunningdon PE29 6HG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

16/12 overfill on tank 2 17/12 VR lines drained. Pict yet to be fixed tank not being used.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

overfill, not recorded
on VR logbook
adv given.

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

07/11/10

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

No document
Adv given

e) STAFF COMPETENCE & TRAINING

No of Staff 9

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

unable to lift tank tops

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Adv to get VR logbook and
record all incidents.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Discussed training records.

Inspector Rephed

Date 29/12/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation