

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

Premises Breckway Service Station Person Seen Deborah Jones  
Address 28a Breckway Ynabry PE7 3NR

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of the district council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Recent test certificate not  
available - Doug checking

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

—

**d) STAFF COMPETENCE & TRAINING**  
No of Staff ☐ No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Tank checked

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes: Site being concerns over  
problem of CPE gas bottle cage,  
site not closed for deliveries.

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

As per P.A

Signed \_\_\_\_\_

Tel /Email \_\_\_\_\_

Received by \_\_\_\_\_

Date/Time \_\_\_\_\_

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.