

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Kates Cabin

Person Seen Cheryl Fretter

Address A1 North

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the  
district council  
Please have up to date Permit in file.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

nothing damaged

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

checked 17th Aug 2018  
3 year by  
Please check annually & record

**d) STAFF COMPETENCE & TRAINING**

No of Staff 5 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

2 competent - training  
records to be updated

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

unable to lift tank tops  
all other signs in place

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

under no management  
since Oct'

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

R.A

Signed

Tel /Email 01954 284 628

Received by

Date/Time 7/9/2018.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.