DO1118

HDC

Environmental Protection Report – Vapour Recovery

Premises H k S	Person seen Charact
Address Bury Road, Ramson com	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y / N Satisfactory Y / N	Inspected Y / N Satisfactory Y / N
Notes She Registre.	Notes 5 mgc 1 over . 21/8/2018.
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff 8 No Questioned 2.
Inspected Y / 科 Satisfactory Y / 和	Inspected Y / ¶ Satisfactory Y / N
Notes Site Registre, in Pores	Notes TRAWING IN PLACE + UP TO DITE.
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y / N Satisfactory Y / N	Satisfactory Y / N
Notes Sign's FADOD. J BUT LOGIBLES	Notes Will Kith and Rin Site.
Does the site have stage II vapour recovery? Y / N	Are procedures in place adequate in the event of any
Notes No.	leaks or spillages? Y / 🗱 Notes
Signed	Tel/Email: 019074 28462: Tel/Email: 019074 28462: Tel/Email: 019074 28462:
Received by P	Date/Time: 12/6/2019.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.