

Environmental Protection Report – Vapour Recovery

Premises Burnsley Person seen _____

Address Berran Walk Huddersfield

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Inspection conducted on behalf of the District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No reported problems, can be
more informed if this is
incorrect

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

To be forwarded

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No certs seen

d) STAFF COMPETENCE & TRAINING

No of Staff 20

No Questioned 1

Inspected Y / N

Satisfactory Y / N

Notes

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Tank tops not lifted

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

Signed [Signature]

Received by [Signature]

Tel/Email: hannah.zepted@cambridge.ac.uk

Date/Time: 11/Sept/19 5.00-12