

# Environmental Protection Report – Vapour Recovery

Premises TESCO SERVICE ST

Person seen \_\_\_\_\_

Address DARTFORD ROAD EYINGBURY PE19 2SA

## OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Vapour Recovery Inspection on behalf of D.C.

### a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

None No incidents

### b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

Stage II V.R cert not available  
LCM stage I valid until 19/8/20

### c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No incidents

### d) STAFF COMPETENCE & TRAINING

No of Staff

☐

No Questioned

☒

Inspected Y / N

Satisfactory Y / N

Notes

### e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

### f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Anomally with Vapour rec  
and offset

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

As per R.A

Signed [Signature]

Received by \_\_\_\_\_

Tel/Email: hannah.stephens@conbridgeh

Date/Time: 17/11/2020 11.50am