

130907

Environmental Protection Report – Vapour Recovery

Premises Shell BuckdenPerson seen Natalinda PereiraAddress 21 North Rd Buckden

(Manager)

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Inspection conducted on behalf of the District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected ☒ Y / ☐ NSatisfactory ☒ Y / ☐ N

Notes

No incidents

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected ☒ Y / ☐ NSatisfactory ☒ Y / ☐ N

Notes

Eds 31 Due 31/10/20

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected ☐ Y / ☐ NSatisfactory ☐ Y / ☐ N

Notes

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff ☐No Questioned ☐Inspected ☐ Y / ☐ NSatisfactory ☐ Y / ☐ N

Notes

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Y / ☐ NSatisfactory ☒ Y / ☐ N

Notes

Tank tops not lifted

Does the site have stage II vapour recovery? ☒ Y / ☐ N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y / ☐ N

Notes

Are procedures in place adequate in the event of any leaks or spillages? ☒ Y / ☐ N

Notes

As per M&K measured.

Signed APTel/Email: 01954 284638Received by N ADate/Time: 17/1/2020

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.