

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises ST NICK'S SERVICE STATION Person Seen MR BAIN

Address CHICHESTER ST, ST NICK'S

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

SITE REGISTER IN PLACE
DELIVERY DECKS ALL CORRECT
NO ALTERATIONS.

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

CERTIFICATE MARCH 18 (FPI)

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

AS B ABOVE.

d) STAFF COMPETENCE & TRAINING

No of Staff 5 No Questioned 2

Inspected Y/N _____

Satisfactory Y/N _____

Notes:

JUST RENEWED CONTRACT WITH
ESSO
ALSO HAVE SURSITE

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

TAGGED BUT LEGIBLE

Does the site have stage II vapour recovery? Y/N _____

Notes:

STAGE ONE ONLY.

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N _____

Notes:

GENERALLY OK
CAR WASHING / HOODS NOW
KEPT AWAY FROM LPG.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N _____

Notes:

Signed APR

Tel / Email 0954 284621

Received by X R. BAIN

Date/Time 28/3/2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.