

ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise S W Highland Person Seen Steve Highland
Address Station Road, Bluntisham

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Site redeveloped Jan 10
Suresite log book.

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Cert 4/11/09

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

New VR pipework
and PV valve.

e) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Owner very knowledgeable.
Staff competent, well
trained + records available.

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

All OK.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

Pipework installed +
pumps capable but
below throughput threshold.

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

Well run site.

Are procedures in place adequate in the event of any leaks or spillages? ☒ Y/N

Notes:

Inspector D. B. Date 3/3/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC