

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Huntingford Service station Person Seen Neroshen
Address London Road St Ives

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapor recovery inspection concluded on behalf of the District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

cos
Due 31/10/2018

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

site register
New pumps new board replaced

d) STAFF COMPETENCE & TRAINING

No of Staff ☒ No Questioned ☒

Inspected Y/N ☒

Satisfactory Y/N ☒

Notes:

Person on hill at time of inspection
not competent.

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

Does the site have stage II vapour recovery? Y/N ☒

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N ☒

Notes:

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email 01954 221 628

Received by _____

Date/Time 4/6/2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.