

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

*W*

Premises Toro Paving Person Seen Jan Clark  
 Address Neillway Pavers

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**  
 As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour Recovery inspection conducted on behalf of the District Council.

Report in file dated 11th March 2014. Please ensure this is to be filed.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected  Y/N Satisfactory  Y/N

Notes:  
 No incidents recorded

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected  Y/N Satisfactory  Y/N

Notes:  
 Please note expires shortly  
 20/9/18

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected  Y/N Satisfactory  Y/N

Notes:

d) STAFF COMPETENCE & TRAINING

No of Staff  No Questioned

Inspected Y/N Satisfactory Y/N

Notes:

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory  Y/N

Notes:  
 VVD cap to be replaced. Pressure release valve *W*  
 No VR sign on tank 4

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory  Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages?  Y/N

Notes:  
 As per risk assessment

Signed *[Signature]* Tel /Email 01954 280 628  
 Received by *[Signature]* Date/Time 5th Sept 2018

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.