

Environmental Protection Report – Vapour Recovery

Premises MORRISONS

Person seen LUCE BYFIELD

Address PARSON GREEN ST IVCS

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Vapour Recovery inspection conducted on behalf of the District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No incidents

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

At time of inspection in date certificate not available.

Forwarded 14/11/2019

PETRONWEST NEXT DUE 8/3/21

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y / N

Satisfactory Y / N

Notes

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Number of certificates not available - to be forwarded

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

Signed Chif

Tel/Email: Hannah Sleptea 01954 284628

Received by _____

Date/Time: 13/11/19