

Environmental Protection Report – Vapour Recovery

Premises DP EATON SOCAN Person seen SHIVA

Address BRAD NORTH RD EATON SOCAN

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected ☒ Y / N

Satisfactory ☒ Y / N

Notes

No incidents

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected ☒ Y / N

Satisfactory ☒ Y / N

Notes

E2 S Enviro 31/9/2020

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected ☒ Y / N

Satisfactory ☒ Y / N

Notes

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff

No Questioned

Inspected Y / N

Satisfactory Y / N

Notes

small set up

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Y / N

Satisfactory ☒ Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

A number of domestic auto tanks requested that they be fenced

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

Signed Chap

Tel/Email: 01954 284 628

Received by _____

Date/Time: 17/11/2020

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.