Environmental Protection Report – Vapour Recovery

Premises Bashy Savia Station	Person seen Steve Cause
Address Old Great Down Rd Sowmy PEZE 5xr	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection your attention is drawn to the following matters:	
Unmarqued site with points margament.	
	rewart personnel but
resolved mov.	
Site is tried and due a re-brand.	
1 1 1 1 1 1 1 1 1	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y / N	Inspected Y N Satisfactory Y / N
Incidents are reported	Notes Sen.
	please and me a copy.
by Areven to control	
cettire.	2514719
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION	d) STAFF COMPETENCE & TRAINING
& TESTING, INVENTORY CHECKING, INSTALLATION &	No of Staff No Questioned
REPAIR WORK (SITE REGISTER)	
Inspected Y N Satisfactory Y / N	Inspected Y / N Satisfactory Y / N
Notes a	Notes
No site mainter	Unmanned sime.
All had certainly.	
All had cetimally.	Please sund me copy of
6	training documents for
	caretakers.
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Language (CA)	
Inspected Y / N Satisfactory Y / N	Satisfactory Y/ N
Connection point booker.	Notes
consisted feature 100 very	Romotely imaraged.
Signe in place atthough	~
Faria.	Charles and a second
4	
Does the site have stage II vapour recovery? Y (N)	Are procedures in place adequate in the event of any leaks or spillages? Y/ N
Notes	
and the second second	Notes DCD box has Kit
All all	and drives train .
the state of the s	8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
- 11 CF 31 2	
	>
Signed	7-115-11 0195 (F 7 6) 17:
Signed	Tel/Email: 0.195 4 78 4 631
Received by Fglly 4Uf	Date/Time: 15/4/19
This report only covers the areas inspected at the time of the in	nspection. It does not indicate compliance with any legislation.