## Environmental Protection Report – Vapour Recovery

Premises Sacre tons Tanen	Person seen Morrow CO.
Address A14 EAST FORSTANTION	87
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
As a result of the inspection your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y / N Satisfactory Y /	Inspected Y / N Satisfactory Y / N
Notes Rigister Keet	Notes  CORTIFICATI OF TEST
	FOR STASE 1+2 21/5/208 Dic 2021
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION	d) STAFF COMPETENCE & TRAINING
& TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	No of Staff No Questioned
Inspected Y / 🗱 Satisfactory Y / 🛍	Inspected Y / N Satisfactory Y / N
Notes Registra in Peres	Notes  ON LINE TRAINING ME  UP 70 DATE.
	UP 70 DATE.
The state of the s	
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y / M Satisfactory Y / M	Satisfactory Y /4
Notes  ALL OR	Notes
	1
Does the site have stage II vapour recovery? Y / N	Are procedures in place adequate in the event of any
Notes	leaks or spillages? Y / 🖥
YS .	Notes
Signed Signed	Tel/Email: 0454
Received by	Date/Firms: 1//10/209

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.