

Environmental Protection Report – Vapour Recovery

Premises MTE Kunkhyden Person seen Rosie Devedsoen
Address 2141 Merck Rd Kunkhyden

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Inspection concluded on behalf of the District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No incidents detected

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

31/10/2019

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

d) STAFF COMPETENCE & TRAINING

No of Staff

5

No Questioned

1

Inspected Y / N

Satisfactory Y / N

Notes

only 2 competent for deliveries

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Tank tops not lifted

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

As per risk assessment.

Signed [Signature]

Tel/Email: _____

Received by [Signature]

Date/Time: 11/Sept/19

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.