ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise John Mos	Person Seen La Karuna
Address Rangey Road, off St Iven Prziskt	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
Inspection conducted by HR Stopled combidgeshire Truding standards on behalf of Kinthy on District	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N Notes:	Inspected Y/N Satisfactory Y/N Notes:
Noincidents	
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned Inspected Y/N Satisfactory Y/N
Inspected Y/N Satisfactory Y/N Notes: No incidents. Michan to be compiled in only reguste.	Notes: Space to my tre haruna Notes: Notes of Pech Cu two D Wisher & A Law Ali' Conhicate para la Sa completed.
c) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N 10 11(-1 1 Chatisfactory Y/N Notes!	Satisfactory Y/N Notes: New Manyement for two Mush (MG kalura)
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages.
Notes:	Notes:
trik steptod	ostoztiz
Inspector	Date

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislatic