

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

**APPENDIX 1**

Premise Total UK Ltd Person Seen Mr M Terry  
Address Hemlington Service St London Rd St Ives

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour Recovery inspection conducted on behalf HDC.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

VR cert required

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**e) STAFF COMPETENCE & TRAINING**

No of Staff 9 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes:

Only 2 competent -> Mr Terry  
& Mr Bishop Training records  
to be updated.

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

enable to lift tank tops  
another 0

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Documents not in date -  
adv given esp as app' backed

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Inspector Alphay Date 13/07/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC