ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premises Toco large and of Person Seen hor Taylork	
Address Mil Way Papan RZ6250	
TO THE AND DECOMMEND ATIONS:	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
Tapar receivery inspection concluded on botheld of the District council	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N Notes:
Notes:	Eurolenk 24/9/15 - Pass
	Gilberco Veeda kul cayalina cert Skor II cayalina 7/7/15
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected YN Satisfactory YN Notes:
Notes:	Notes.
whistle both in place.	
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
tes:	Notes: Apregad to be a vestion site.
Does the site have stage II vapour recovery YYN	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes:
Signed Tel /Email 01959 254 678	
Received by Alfalla Date/Time 4) 16	

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.