

Environmental Protection Report – Vapour Recovery

Premises BLUNTISHAM SERVICE STATION Person seen _____
→ SLI HIGHLAND LTD
Address PE28 3PA

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of the District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

No incidents
Visual inspection 13/1/2020
D.M. PETROLEUM SERVICES LTD

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

Not seen - asked for
information to be forwarded

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No incidents

d) STAFF COMPETENCE & TRAINING

No of Staff

5

No Questioned

☒

Inspected Y / N

Satisfactory Y / N

Notes

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Tank tops not fitted with
VLE KSL

Does the site have stage II vapour recovery? Y / N

Notes

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

21 staff 5 competent

Are procedures in place adequate in the event of any
leaks or spillages? Y / N

Notes

As per RA

Signed [Signature]

Received by _____

Tel/Email: hannah.stepped@cambridgehive

Date/Time: 25/2/2020 8.00.16

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.