

REPORT - VAPOUR RECOVERY

Premises NATIONAL PFC Person Seen JACK WAT
 Address NORTHWOOD ROAD ST IVES

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

NEW SITE

UNREGISTERED DEVIATIONS

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N Satisfactory Y/N

Notes:

CERTIFICATE IN PLACE
NEW SITE
(WESTFIELD)

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

GUIDANCE GIVEN
TO RE-SITE

d) STAFF COMPETENCE & TRAINING

No of Staff 21 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes:

TRAINING ONGOING, 75%
COMPLETE. GUIDANCE GIVEN

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

ALL SIGNS IN PLACE
LOCKED & SEALED

Does the site have stage II vapour recovery? Y/N

Notes:

STAGE II - NEW INSTALLATION

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

ONE SIGN TO MANAGE
AS ABOVE

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

IN PLACE & GUIDANCE GIVEN

Signed VP

Tel / Email 01954 224021

Received by JACK WAT

Date/Time 21 May 2007

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation