ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise KULTON BROTHEIS	Person Seen Likes HCMPSTED
Address BULY ROAD RAMSE PEZEINC	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK Inspected N Notes:	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual) Inspected Y/N Satisfactory Y/N Notes: TE + J 24/12/19
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER) Inspected YN Satisfactory YN Notes:	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned Inspected No Satisfactory Notes: ALL UL
c) VAPOUR RECOVERY CONNECTIONS & SIGNS Inspected Y/N Satisfactory (Y/N Notes: Does the site have stage II vapour recovery? Y/N Notes:	f) SITE MANAGEMENT & OTHER COMMENTS Satisfactory YN Notes: WCLL MANAGEMENT & OTHER COMMENTS Satisfactory YN Notes: Are procedures in place adequate in the event of any leaks or spillages? YN Notes:
Inspector_Kiliayath	Date 11th August 2009

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC