

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

**APPENDIX 1**

Premise BRAMPTON HUT CONNECT

Person Seen MR ROGER HARRISON

Address A1/A14 GREAT NORTH ROAD, BRAMPTON, HUNTINGDON

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

NO INCIDENTS

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

TESTED 19/01/09.

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK.

**e) STAFF COMPETENCE & TRAINING**

No of Staff 8

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK.

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

ALL OK

Does the site have stage II vapour recovery? Y/N

Notes:

ALL OK.

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

WELL RUN SITE

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

ALL OK.

Inspector KIRSTY DRAYCOT - CCC TRADING  
STANDARDS

Date 12/10/09.

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC