

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise BRAMPTON HUT CONNECT

Person Seen MR ROGER HARRISON

Address A1/A14 GREAT NORTH ROAD, BRAMPTON

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

NO INCIDENTS -

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

TEST DATED 11/12/09.

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

OK.

e) STAFF COMPETENCE & TRAINING

No of Staff 17

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

ELECTRONIC TRAINING RECORDS -
UP TO DATE.

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

OK.

Does the site have stage II vapour recovery? Y/N

Notes:

OK.

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

WELL MANAGED SITE

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

OK.

Inspector KIRSTY DRAYCOTT, CCC TRADING

Date 15/10/10

STANDARDS ON BEHALF OF HUNTINGDON DISTRICT COUNCIL

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation