

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Brompton Hat Service St. Person Seen Mr C Berridge  
Address Brompton, Henbydon

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Conducted on behalf of Henbydon District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

nothing documented.  
Section in site register to  
required

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

**d) STAFF COMPETENCE & TRAINING**

No of Staff 21

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

17 staff + 4 managers

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

Unable to lift tank to 20

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

NEW manager

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

RA.

Signed

Tel /Email

01954 284621

Received by

Date/Time

20/08/13

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.