REPORT - VAPO	AL PROTECTION OUR RECOVERY	APPENDIX 1
Premise Tenco pervice station	Person Seen	Julie Oatley
Premise Tenco Dervice station Person Seen Julie Ochley Address Berford Read, Eyresbury, St Neoto PE 19 25R		
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is/drawn to the following matters: A behalf lund a Den Den Coroll.		
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFIC VALVES (Annual)	ATE FOR PRESSURE RELIEF
Inspected Y/N Satisfactory Y/N	Inspected Y/N	Satisfactory Y/N
Notes: No enudent's received	Notes: 18/12/09	りしつ
	v , v	つりい
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	e) STAFF COMPETENT No of Staff No	CE & TRAINING Questioned
Inspected Y/N Satisfactory Y/N	Inspected Y/N	Satisfactory Y/N
Notes No incidents	Motos: V. R explained.	
	V. K SCOCING	, od ,
		,
TAKE DESCRIPTION OF THE PROPERTY OF THE PROPER		
c) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS	
Inspected Y/N Satisfactory Y/N	a .	Satisfactory Y/N
Morsen due to high Llader	Leti run site	*
12001. Please see rechlicals a white		*
Does the site have stage II vapour recovery	Are procedures in place adequate in the event of any leaks or spillages? Y/N	
Notes:	Notes:	
Inspector_H.R. Steplerd (Trading Standards) Date 08/12/09		

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.