

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Tesco Service Station Person Seen Danni Cresswell
Address Barford Road St Neots

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

No incidents reported.

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

Tested by Eurotank on
6/1/2011.

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

Certificate dated 6/1/11.

e) STAFF COMPETENCE & TRAINING

No of Staff

No Questioned

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

Training records
inspected.

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

All OK.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

Relatively new site.

Are procedures in place adequate in the event of any leaks
or spillages? ☒ Y/N

Notes:

Inspector Sharon Whittington Date 29/7/2011

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC