

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise PACE CATION Saxon Person Seen K. Sasi
Address Great North Rd, Coton Saxon St Neato

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

6/10/11 PASS.

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

advised to produce document
for dry VR works

e) STAFF COMPETENCE & TRAINING

No of Staff

No Questioned

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

2 cashiers 1 manager
website monitored by
Parrbanks

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected ☒ Y/N

Satisfactory ☒ Y/N

Notes:

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

site register in good order

Are procedures in place adequate in the event of any leaks
or spillages? ☒ Y/N

Notes:

Inspector Chphyl

Date 18/01/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC