

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises MRH BP GUYAN SOXON

Person Seen Dineshkumar Ramaraj

Address 78 Great North Road Cantonment PE19 8ES

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of the District Council.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

Gas - tested for stage 1 & 2  
Dated next test 31/10/14  
PASS

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

No incidents

**d) STAFF COMPETENCE & TRAINING**

No of Staff

No Questioned

Inspected Y/N

Satisfactory Y/N

Notes:

4 staff hold SMTS competent  
persons.

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

\* Tank 4 unleaded requires  
\* VR sign  
that pump capacity to be  
investigated.

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Organised documents.  
 hoses for unleaded pumps 3 & 5  
broken pump & need replacing.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

R.D.

Signed

[Signature]

Tel /Email

01954 284 628

Received by

[Signature]

Date/Time

31/03/14

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.